

IDEAL BEARING / Quality Control For IB01 Products

Working Step 1: Sintering Material

Equipment: Sintering Stove

Checking Tools: Micrometer & Ocular Estimate

Checking Points: Thickness Tolerance & Out Looking

Details: 1. Check the tolerance of wall thickness.

2. Keep good appearance, no scratch on the two surfaces.

Working Step 2: Cutting Circumference

Equipment: Punch Press Machine

Checking Tools: Vernier Caliper

Checking Points: Circumference Size

Details: 1. Keep good appearance, no scratch on the two surfaces.

2. Check the tolerance of wall thickness.

3. Control the burrs.

Working Step 3: Remove Burrs

Equipment: Belt Sander

Checking Tools: Ocular Estimate

Checking Points: Two Ends Burrs

Details: 1. Keep good appearance, no scratch on the sliding layer.

IDEAL BEARING / Quality Control For IB01 Products

Working Step 4: Cutting Length

Equipment: Cutting Machine

Checking Tools: Vernier Caliper

Checking Points: Length Size

Details: 1. Keep good appearance, no scratch on the sliding layer.
2. Control the burrs.

Working Step 5: Bending End

Equipment: End Bending Machine

Checking Tools: Ocular Estimate

Checking Points: Bending Radian

Details: 1. Control Bending Radian.

Working Step 6: Rolling

Equipment: Rolling Machine

Checking Tools: Ocular Estimate

Checking Points: Roundness & Out Looking

Details: 1. Keep good appearance, no scratch on the sliding layer.
2. Control the small split.

IDEAL BEARING / Quality Control For IB01 Products

Working Step 7: Forming

Equipment: Hydraulic Press Machine

Checking Tools: Ring Gauge for Outer Diameter; Housing & Plug Gauge for Inner Diameter;
Micrometer for Wall Thickness

Checking Points: Outer Diameter, Inner Diameter and Wall Thickness

Details: 1. Keep good appearance, no scratch on the sliding layer.

2. Check the tolerance of outer diameter, inner diameter and wall thickness.

Working Step 8: Chamfering

Equipment: Chamfering Machine

Checking Tools: Vernier Caliper & Universal Angle Gauge

Checking Points: Inner Chamfering, Outer Chamfering and Length

Details: 1. Keep good appearance, no scratch on the outer surfaces.

2. Control the length.

Working Step 9: Polishing

Equipment: Centrifugal Concussive Machine

Checking Tools: Ocular Estimate

Checking Points: Outer Looking

Details: 1. Keep good appearance, no scratch on the outer surface.

2. Avoid the products being get rusted.

IDEAL BEARING / Quality Control For IB01 Products

Working Step 10: Tin Plated

Equipment: Tin Plated Machine

Checking Tools: Ocular Estimate

Checking Points: Appearance

Details: 1. Keep good appearance, no tin on the sliding layer.

Working Step 11: Packing

Equipment: People

Checking Tools: Ocular Estimate

Checking Points: Appearance

Details: 1. Reject the bad appearance products.

2. Reject the bad sliding layer products.

3. Reject the bad split products.

4. Reject the bad chamfer products.